## **Idaho PUC Pipeline Safety Inspection Summary**

Inspector(s):	Perkins		Date(s):	25-Aug-20
Company/Owner: Intermountain Gas Company		Unit /ODID:	0100	
Company/Owner:	Intermot	intain Gas Company	Unit/OPID:	8160
Inspection Type & Time (2	 1 day)	Total I	nspection Days:	1
Standard: Construction:  M/M: Follow-up:	: 1 Training:	(T)(D) Integrity Management:  Damage Prevention:		
IVI/IVI:   FOIIOW-up:		Damage Prevention:	D&A:	
Inspection Summary				
A construction inspection was performed on Das-co, a contractor for Intermountain Gas Company.				
25 Aug 2020: (1.0 Construction) Observed a Das-co crew installing ¾" mains to 953 W Tida St and 4481 Girasolo Ave in Meridian Idaho. All procedures were followed. Typed up report.  Areas observed during this project were: Excavating, line locating, plastic pipe joining, pressure testing, bedding/backfilling  Attachments: IPUC Form 4 Construction Inspections Das-co daily Itineraries located in file for the project. OQ's for all observed employees are located in file for the project. Pictures of Job tickets.				
Corrective Action Required:		ow-up Required: Ye		
	X	7	by (date):	
Inspector (Lead):  Bruce Perkins	1 Sentillas	het a	<b>Date:</b> 8/25/2020	
Reviewer:	11/19/11	11/1	0/25/2020 Date:	
Darrin Ulmer	1 Was Hills.	4/1/6	26 Aug 202	10